

REPORT OF CHANNEL CONDITIONS 100 TO 400 FEET WIDE <i>(EP 1130-2-520)</i>						PAGE 1 OF 1	
						DATE 12 August 2008	
TO: Navigation Interests				FROM: U.S. Army Engineer District, Baltimore P.O. Box 1715 Baltimore, Maryland 21203-1715			
RIVER/HARBOR NAME AND STATE Honga River Dorchester County, Maryland					MINIMUM DEPTHS IN CHANNEL ENTERING FROM SEAWARD		
NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER <i>(feet)</i>	MIDDLE HALF <i>(feet)</i>	RIGHT OUTSIDE QUARTER <i>(feet)</i>
		WIDTH <i>(feet)</i>	LENGTH <i>(miles)</i>	DEPTH <i>(feet)</i>			
Honga River Station 11+200 to 24+635	1/May/200	60	3	7		2	
REMARKS <i>(Continue on reverse)</i> All depths refer to MLLW for the 1983-2001 tidal epoch. This information represents the results from surveys conducted on the dates shown (1 May 2008) and can only be as indicating the general conditions at that time. Lenth of channel is reported to the nearest mile. The actual length is 2.54 miles. Depth in Middle Half equals minimum depth in full channel. MH= E1531088.13, N247465.70 (1.5')							